

## Field Log

### 2021 Field Care

2-17	Mowed runway – JC	7-14	Mowed – JC
3-4	Runway fertilized – JC Sprayed Parking area with grass killer	7-15	Watered - JL
3-15	MouseX deployed in Club House and mower shed. - JC	7-22	Watered –MB
3-29	Mowed runway – JC	7-27	Watered –MB Runway Mowed – JC
4-10	Mowed – JC	8-3	Watered –JC
4-15	Mowed & sprayed – JC	8-4	Runway Mowed – JC
4-20	Mowed & overseeded – JC Tested sprinklers	8-5	Watered – DF – (flow weak)
4-27	Mowed and aerated runway – JC	8-9	Watered (6 pods) East end – MB
4-29	Mowed the rest - JC	8-10	Watered (6 pods) West end – JC
5-6	Mowed and aerated runway – JC Overseeded runway in front of pits Watered runway	8-11	Runway Mowed – JC
5-11	Mowed & sprayed – JC	8-16	Watered (6 pods) East end – DF
5-13	Watered –MB	8-19	Runway Mowed – JC & AW
5-18	Mowed & sprayed – JC	8-19	Watered (6 pods) West end – BW
5-20	Watered - JL	8-23	Watered (6 pods) East end – MB
5-21	Mowed – JC	8-26	Watered (6 pods) West end – MB
5-25	Runway Mowed – JC	9-2	Watered (6 pods) West end – JL
6-3	Watered – MB	9-6	Watered (6 pods) East end – JL
6-9	Runway Mowed – JC	9-9	Watered (6 pods) West end – DF
6-9	Watered – dc	9-13	Runway Mowed – JC
6-15	Mowed and rolled– JC	9-13	Watered (6 pods) East end – MB
6-21	Runway Mowed – JC Watered – JC	9-23	Runway Mowed – JC
7-1	Watered – BW	10-1	All mowed – JC
7-6	Runway Mowed – JC	10-7	Runway Mowed – JC
7-8	Watered –MB	10-14	Runway Mowed – JC
		10-21	Runway Mowed – JC
		10-30	Runway Mowed – JC
		11-11	Runway Mowed – JC
		11-19	Runway Mowed – JC

### Field Improvements

8-19-17	Runway and Swamp Plowed		
8-26	Runway rototilled	8-31	Smoothed and rolled
9-25	Watered	9-16	Seeded and rolled
9-30	Grass starting to come up		
10-17	First mowing of new grass		
9-24-19	New pit cover installed.		
7-2-20	Club house pressure washed – RD Junk removed from club house - JL & RD. Hauled to dump – JC		
10-5-20	Pit cover now has metal roof. – Work party		
4-20-21	Overseeded runway - JC		
5-6-21	Overseeded runway in front of pits - JC		

### Fertilizer applied

07-09-12	05-07-13	07-28-14	09-26-14	05-10-15	05-18-16
09-19-16	06-30-17	07-23-18	1/2 bag	09-19-18	1/2 bag
3-11-19	1/4 bag	04-23-19	2 bags	04-23-19	2 bags Weed & Feed
8-5-19	2 bags	03-25-20	2 bags	03-25-20	2 bags Weed & Feed
				06-11	2 bags 16-16-16

## Sand applied

05-17-15, 05-07-16, 09-19-16, 08-16-17, 09-20-18, 09-18-19, 10-19-20,

## Gravel applied to parking area

11-24-20 12-08-20

## Sprinkler system

04-30-18 5 more pods added to existing 6 pod system

## Weather Station

05-05-18 New La Crosse weather station installed. Two "C" cells in outdoor unit, three "AA" cells for indoor unit.

01-24-19 Bracket holding outdoor unit repaired. Batteries replaced on indoor unit.

10-29-19 Bearings floppy, removed to see if it can be repaired.

10-30-19 Bearings oiled and glued back into plastic housing, seem ok now.

12-20-20 Two "C" cells in outdoor unit, three "AA" cells for indoor unit replaced.

02-17-21 Speed part of outside unit not working (turning). Replaced upper bearing.



## Windsock

Airport Windsock Corporation Product 18"x60" Aviation Quality Windsock  
Flat measurements 28 1/2 " x 58" x 14" 14 brass eyelets

07-16-12 Spare installed

06-05-15 New one installed

03-10-18 Spare installed

04-21-20 Two new ones purchased






SPARES as of 4-21-20

One Hobby King sock, Two Airport Windsock Corporation new socks.

9-26-20 Hobby King Windsock installed at East end of field.

08-11-21 Spare installed



Old

New

**Toilet**

06-04-20 Above all Sanitation – delivered new toilet – by the month.

11-06-20 Removed



**To Do**

Geotex - North South Runway - needs a PLAN as to how it will be managed  
**FIELD FLYING RULES and Designated Flying Area will need to be updated.**